

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2021

Submitted Date:

06/16/2021

Document Number:

693505225

## FIELD INSPECTION FORM

Loc ID 318327 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241109	WELL	PR	03/20/1995	OW	123-08897	FRANK J VOGL NAV 2	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well head sign starting to fade may need to be replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: electric motor, electric panel and breaker box.		
Corrective Action:	Comply with rule 606.	Date:	07/16/2021
Type	OTHER		
Comment:	Flowline and Crude Oil Transfer Line Statuses. (marking and LOTO)		
Corrective Action:	Comply with rule 1101 a	Date:	07/16/2021
Type	OTHER		
Comment:	Mechanical issues: Electric motor not connected and electric meter has no power to site.		
Corrective Action:	Comply with rule 608 e	Date:	07/16/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:		#		corrective date
Prime Mover		# 1		
Comment:	Electric motor not connected to power and PU.			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Ancillary equipment		# 1		
Comment:	Electric panel			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241109 Type: WELL API Number: 123-08897 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection flow line valvs were LOTO.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 11/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday June 16, 2021 at approximately 3:17PM, I, Inspector Randy Silver, conducted an on-site inspection.                      Location: Frank J Vogl Nav #2                      Operator: KP Kauffman                      API#:123-08897                      County: Weld                      While there, I observed a shut in well site.                      During this inspection the following possible compliance issues were observed:                      Mechanical issue: Rule 608 e Corrective action date of 7-16-21 See photo 3,4,5,6                      Unused equipment: rule 606 Corrective action date of 7-16-21 See photo 3,4,5,6                      Riser: Rule 1101a Corrective action date of 7-16-21 See photo 7                      Weather conditions: Dry and hot.                      This well appears not to be producing due to the flow line valves being LOTO. Submit reason for valves being LOTO. Tank battery is located off site GPS40.08535, -104.87841                      Spindle Consolidation Battery #6.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	06/16/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402721208	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457488</a>
693505227	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457486">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457486</a>