

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



location



location

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



location



location

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Unused equipment



Debris

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Debris



location

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Container (full of fluid) in front of tank battery has No labeling nor is it in a containment.

Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Lack of stabilization/compaction



One of the sediment traps along access road



Caerus Piceance LLC
ELU #8905C-24
Location # 316505



One of the sediment traps along access road



One of the sediment traps along access road



Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion



Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion



Caerus Piceance LLC
ELU #8905C-24
Location # 316505



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion

