

Inspection Photos

API: 009-06047

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021

Inspection Photos



Photo 1. The well sign does not comply with 605. Incorrect Operator Emergency number and missing information. Name was updated. Missing tank NFPA labeling and INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021

Inspection Photos



Photo 2. The fencing around the pump jack has been fixed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021

Inspection Photos



Photo 3. The tank is marked as not in use and labeled Produced Water. Next photo shows fluids inside the tank which apparently the tank is in use. Secondary containment is inadequate to contain 150% of the volume of the tank.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021

Inspection Photos




Photo 4. View of fluids inside the tank. Tank is labeled Produced Water. The netting appears to have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021

Inspection Photos



Photo 5. There is a metal panel laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06047 | Date: 6/21/2021