

Inspection Photos

API: 009-06082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing east toward the location. There is no well sign posted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 2. Missing tank NFPA labeling and missing INFO per 605.h..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 5. View of fluids inside the tank. Tank is labeled Produced Water. It appears to be solidified salty produced water. The netting on the tank is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 3. There appears to have been a leak at the tank due to stained soil in this area. If tank contains produced salty water, this can impact the soil and crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 5. Secondary containment is inadequate to contain 150% of the volume of the tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021

Inspection Photos



Photo 6. There is exposed electrical wire on the ground and panel box. All unused supplies and equipment need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 6/21/2021