

Inspection Photos

ID:429852

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing southwest toward the location which is adjacent to County Rd. 44.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 2. There is oil stained soil near the Produced Water tank. The tank is labeled produced water but appeared to contain oily fluid. Netting was over the top of tank. Additionally the berm does not appear to be sufficient to contain a spill.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 3. There is an exposed electric utility that remain at red arrow. There is oil stained soil shown at yellow arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 4. There is oily waste inside this containment which is near the top of the containment and appears to have spilled over. The oily waste has not been removed and properly disposed since last inspection. A dead bird was previously observed in the oily fluid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 5. The facility sign is posted but contains incomplete and inaccurate information. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 6. The berm around the tank vessel is inadequate in size and has animal burrows in it. The berm has not been repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 7. On the backside of the metal panels is unused equipment. There is various supplies and waste stored in the tanks. Unused equipment/supplies has not been removed. Previous corrective action was not performed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos




Photo 8. Aerial imagery shows a storage yard behind the compressor facility. The storage yard no longer exists however, the disturbance area needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 9. Facing southeast behind the compressor facility. There is undesirable weeds throughout this disturbed area which weeds will need to be controlled and the disturbance area reclaimed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 10. Facing northeast behind the compressor facility. There is undesirable weeds throughout this disturbed area which weeds will need to be controlled and the disturbance area reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021

Inspection Photos



Photo 11. Facing west toward the surrounding undisturbed pasture which consists of desirable native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 429852 | Date: 6/21/2021