

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Network: Jun 22, 2021 at 1:31:37 PM MD
Local: Jun 22, 2021 at 1:31:37 PM MD



Network: Jun 22, 2021 at 1:31:52 PM MD
Local: Jun 22, 2021 at 1:31:52 PM MD

Photo #4135 from entrance to location.

Photo #4136 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Photo #4146 Location lacks stabilization.



Photo #4147 No form of tracking BMP Located at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Photo #4137 Multiple places with Rill erosion occurring on location.



Photo #4138 Multiple places with Rill erosion occurring on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Photo #4140 No velocity checks located in ditches.



Photo #4141 No velocity checks located in ditches.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Photo #4142 Sediment trap insufficient.



Photo #4144 Sediment trap insufficient.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-67S95W /6SWNE

Location ID: 334957



Photo #4145 Sediment migration and gully erosion occurring downstream of location and access road BMP's.