

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/21/2021

Submitted Date:

06/23/2021

Document Number:

690201700

**FIELD INSPECTION FORM**
 Loc ID 320975 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
LEVENGGOOD JOHN		jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205636	WELL	PR	07/16/1987	GW	009-06047	STATE OF COLORADO 1-15	RI

**General Comment:**

This is a follow up of the previous inspection #690201501.  
 Previous inspection corrective actions have not been completed.  
 See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The tank label does not comply with 605. Missing tank NFPA labeling and missing INFO.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/05/2021

**Emergency Contact Number:**

Comment:	The well sign does not comply with 605. Invalid Operator Emergency number. Operator Name was updated.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/05/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	The fencing around the pumpjack was repaired but the fencing around the tank was not. The fence panel is still laying on the ground.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	05/20/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1	200 BBLs	Open Top		,	
Comment:	The netting on the tank has been repaired.					
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate			Inadequate	
Comment:	There is inadequate secondary containment around the tank.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 06/03/2021

**Venting:**

Yes/No				
Comment:				
Corrective Action:				
			Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201702	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462108</a>