

# Inspection Photos

API: 009-06162

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/21/2021



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06162 | Date: 6/21/2021

## Inspection Photos



**Photo 1.** Facing east at former tank site. This area has not re-established a crop at 50'x40' area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06162 | Date: 6/21/2021



## Inspection Photos



**Photo 2.** Drone aerial photo of tank battery sited which has not re-established crop cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06162 | Date: 6/21/2021



## Inspection Photos



**Photo 3.** Drone aerial photo facing east toward access road and location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06162 | Date: 6/21/2021

## Inspection Photos



**Photo 4.** Drone aerial photo facing west toward access road and location shown at red arrow. It appears the crop has re-established along the access road and location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06162 | Date: 6/21/2021