

Inspection Photos

API: 009-06134

Operator: SAMSON OIL COMPANY

Inspection Date: 6/21/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06134 | Date: 6/21/2021

Inspection Photos



Photo 1. Approximately 100' northeast of the location is an abandoned pipeline user which must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06134 | Date: 6/21/2021

Inspection Photos



Photo 2. Facing south toward the location. There is no vegetation growth on this area of the location approximately 70'x70'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06134 | Date: 6/21/2021

Inspection Photos



Photo 3. The perimeter fence remains in disrepair around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06134 | Date: 6/21/2021

Inspection Photos



Photo 4. There is another pipeline riser that remains at the location that has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06134 | Date: 6/21/2021

Inspection Photos



Photo 5. Facing northwest towards area that remain devoid of vegetation growth.

