

Inspection Photos

API: 009-05157

Operator: PONCHO PRODUCTION COMPANY

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-05157 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing southeast toward the location. There is a water well and stock tank at the location belonging to the landowner. The black two tanks shown were equipment from the well site which need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 6/21/2021

Inspection Photos



Photo 2. There are two tanks, pipe riser, and meter run that remain. All equipment should have been removed within 3 months of well abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 6/21/2021

Inspection Photos



Photo 3. The meter run and shed remain at the location. All equipment should have been removed within 3 months of well abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 6/21/2021

Inspection Photos



Photo 4. Facing southeast at the location. There are areas of the location with no vegetation growth which will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 6/21/2021