

Inspection Photos

ID# 292827

Operator: JONES ENERGY LTD

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing southeast toward the location. There are undesirable weeds and areas with no vegetation growth at the location. The location is being farmed around and has not been returned to cropland production



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 2. Southwest side of the location facing north. There are undesirable weeds and areas with no vegetation growth at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 3. Facing southeast along the southern side. The location is being farmed around and has not been returned to cropland production. There are undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 4. Southeast side of the location facing northwest. There are undesirable and noxious weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 5. North side of the location facing west. Undesirable weeds are growing throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021

Inspection Photos



Photo 6. The pipeline riser remains at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 292827 | Date: 6/21/2021