

Inspection Photos

6/23/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335815

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 1: Photo taken from the south end of the Location, facing northwest. Photo provides an overview of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 2: Photo taken from the North end of the Location facing southeast. Photos 2-5 provide and overview of the Location from southeast, south, southwest to west. Photos show interim reclamation of areas not needed for production has not been performed in accordance with 1003 Rules and Corrective actions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 3: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 4: See comments under photo 2. .



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 5: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 6: Photo taken from the southwest end of the Location, facing west. Photos 6-8 provide an overview of the Location from west, northwest to north. Photos show interim reclamation of areas not needed for production has not been performed in accordance with 1003 Rules and Corrective actions.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 7: See comments under photo 6.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 8: See comments under photo 6.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 10: Photo taken from the west end of the Location, facing north. Photos show BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 11: Continued from photo 10. Photo shows slope drain has not been properly secured, or constructed with an appropriate outlet in accordance with good engineering practice.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 12: Photo taken from the west end of the Location, facing west. Photo shows BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 13: Photo taken from the south end of the Location, facing southeast. Photo shows BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 14: Photo taken from the southeast end of the Location, facing southeast. Photo shows soil stockpile. Photo also shows BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 15: Photo taken from the east end of the Location, facing northeast. Photo shows BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 16: Photo taken from the east end of the Location, facing east. Photo shows BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 17: Photo taken northeast of the Location, facing southwest. Photo provides an overview of the Location, and shows that interim reclamation has not been performed in accordance with 1003 Rules. See photo 1 for aerial image of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 18: Photo of the tank battery on the southwest end of the Location. See inspection #701101419 for corrective actions regarding signage.

