

Inspection Photos

6/23/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 323893

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 1: Photo taken from the east end of the Location (from the access road) facing south. Previous inspections documented that between 2011 and 2014, the access road in this area was further expanded east (red arrow). Previous inspections required Operator to reclaim the original access road (yellow) including, but not limited to, compaction alleviation, recontouring/regrading and revegetation. Photo shows that the original access road has not been reclaimed. Photo insert bottom right shows access road areas that were required to be reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 2: Photo taken from the access road southwest of the Location, facing northeast. Photo shows access area to a radio tower. This road is required to access facility; oil and gas access roads south and east require reclamation (photos 3-7).



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 3: Photo taken from the access road that travels from the southwestern end of the Location, facing east. Photo shows a section of the original oil and gas access road, that accessed the Location from the south. Access road is not necessary and required reclamation. Photo shows Operator has not reclaimed the access road per the corrective actions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 4: Photo taken from the former access road, southeast of the Location, facing north. Photo shows access road has not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 5: Photo taken from the access road that travels from the southwestern end of the Location, facing south. Photo shows Operator has not reclaimed the access road per the corrective actions.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 6: Continued from photo 3. Photo shows access road has not been reclaimed. Photo also shows stormwater erosion degradation observed on the road. Temporary stormwater BMPs required until reclamation has been performed, at which point control measures to stabilize the seeded soil are required.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 7: Continued from photo 4. Photo taken from the access road that travels from the southwestern end of the Location, facing north. Photo shows Operator has not reclaimed the access road per the corrective actions. Photo also shows stormwater erosion degradation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 8: Photo taken from the access road that travels northwest of the Location, facing north. Photo shows reclamation activities have been performed. Corrective action required Operator to implement BMPs to stabilize the seeded soil. Photo shows BMPs to stabilize the seeded soil are missing or insufficient/inadequate; unable to find evidence that stabilization control measures have been installed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 9: Photo taken from the access road that travels northwest of the Location, facing south. See comments under photo 8.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 10: Photo taken from the access road that travels northwest of the Location, facing west. See comments under photo 8.