

Inspection Photos

6/23/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324441

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 1: Photo taken from north end of the Location, facing south. Photos 1-3 provide and overview of the Location from south, southwest to west. Photo shows control measure to stabilize/protect the production areas, or to prevent off-site sediment transport and tacking remain missing or insufficient

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



20210623

Photo 4: Photo taken from the Location entrance, facing east. Photo shows tracking and off-site sediment concerns remain evident; control measure to stabilize/protect the production areas and access road, or to prevent off-site sediment transport and tacking remain missing or insufficient



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 5: Photo taken from interim areas on the north end of the Location, facing west. Photo shows undesirable weedy plant establishment remains evident. Unable to find evidence that additional reclamation activities have been performed.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324441



Photo 6: Continued from photo 5. Photo shows noxious weed (bindweed) establishment on the interim areas of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 7: Photo taken from interim areas on the northwest end of the Location, facing southwest. Photo shows undesirable weedy plant establishment remains evident. Unable to find evidence that additional reclamation activities have been performed.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 8: Photo taken from interim areas on the southwest end of the Location, facing north. Photo shows undesirable weedy plant establishment remains evident. Unable to find evidence that additional reclamation activities have been performed.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 9: Photo taken from the southeast end of the Location, facing east. Photo shows sediment trap.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 10: Continued from photo 9. Phot shows sediment trap has not been constructed with geotextile lining in accordance with good engineering practices

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324441



Photo 12: Photo taken from the northwest corner of the Location, facing north. Photo shows hydromulch has been applied to the soil stockpile. Photo also shows undesirable weedy plant establishment remains evident

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324441



Photo 13: Continued from photo 12. Photo shows undesirable and noxious weed establishment at the soil stockpile.