

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2021

Submitted Date:

06/24/2021

Document Number:

699304054

FIELD INSPECTION FORM

Loc ID 321337 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|-----------------|
| , | | cogccinspection@pdce.com | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 206729 | WELL | PR | 04/01/2020 | GW | 013-06224 | CLAY 1 | PR |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | fabricated steel pipe | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | automation | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | card indicates that calibration is past due, Provide calibration records or calibrate meter. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR). | | |
| Corrective Action: | Comply with Rule 430 | Date: | 07/24/2021 |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------|---------------------------------|-------|
| Type: Bradenhead | # 1 | |
| Comment: | appear to be plumbed to surface | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | OTHER | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 160 bbl | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Wells Served By Facilities Above**AirsID**

| | | |
|------------|------------|--------|
| API Number | API Number | AirsID |
| 013-06224 | | |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 206729 Type: WELL API Number: 013-06224 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 09/18/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 6/24/2021 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a PDC Energy Inc. location:</p> <p style="text-align: right;">Clay 1 at API #05-013-06224 in</p> <p>Boulder County Colorado.</p> <p>While there, I observed a wellsite and tank battery, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>430 measurement of gas: Card in meter box indicates calibration is not current, CA date 7-24-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 06/24/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699304055 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464227 |