

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/18/2021

Submitted Date:

06/18/2021

Document Number:

700702882

**FIELD INSPECTION FORM**

Loc ID 335898	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORT WORTH State: TX Zip: 76102				<b>Findings:</b> 17 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Sutton, Derek		derek_sutton@xtoenergy.com	
clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Dooling, Jessica	832-624-0810	jessica.dooling@exxonmobil.com	
, Caerus		COGCC.inspections@caerusoilandgas.com	
Thomson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294138	WELL	PR	01/01/2021	GW	103-11157	PICEANCE CREEK UNIT 297-12A1	PR
294142	WELL	PR	02/13/2010	GW	103-11158	PICEANCE CREEK UNIT 297-12A2	PR
294201	WELL	PR	04/01/2020	GW	103-11160	PICEANCE CREEK UNIT 297-12A3	PR
294202	WELL	PR	02/13/2010	GW	103-11161	PICEANCE CREEK UNIT 297-12A7	PR
294203	WELL	PR	01/01/2019	GW	103-11162	PICEANCE CREEK UNIT 297-12A9	PR
294204	WELL	PR	01/01/2021	GW	103-11163	PICEANCE CREEK UNIT 297-12A5	PR
294205	WELL	PR	07/01/2017	GW	103-11164	PICEANCE CREEK UNIT 297-12A6	PR
294206	WELL	PR	07/17/2009	GW	103-11165	PICEANCE CREEK UNIT 297-12A8	PR
294207	WELL	PR	05/31/2012	GW	103-11166	PICEANCE CREEK UNIT 297-12A4	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 6/17/2021 at approximately 0900, I, Inspector Scott Ramsey, conducted a routine inspection at XTO T14X-13G, at Location # 316259 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

During this inspection the following possible compliance issues were observed:

1. Debris around wells

2. Regulator was leaking gas (I contacted Zack Simpson the lead for XTO and he informed me that someone would be out to fix it immediately)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Regulator at manifold was leaking gas (I contacted Zack Simpson the lead for XTO and he informed me that someone would be out to fix it immediately)		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Random debris around well heads		
Corrective Action:	remove debris		Date: 06/25/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 9		corrective date
Comment:	Braden heads have a manual gauge for monitoring		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	chemical tanks at manifold in metal containments		
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:

Inspector Name: Ramsey, Scott

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	294138	Type:	WELL	API Number:	103-11157	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294142	Type:	WELL	API Number:	103-11158	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294201	Type:	WELL	API Number:	103-11160	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294202	Type:	WELL	API Number:	103-11161	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294203	Type:	WELL	API Number:	103-11162	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294204	Type:	WELL	API Number:	103-11163	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294205	Type:	WELL	API Number:	103-11164	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294206	Type:	WELL	API Number:	103-11165	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Waddles				
Berms						
		Ditches				
		Sediment Traps				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area, BLM stipulations area and CDPHE Reg. 42 area.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402723657	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459277">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459277</a>
700702885	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459274">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5459274</a>