

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2021

Submitted Date:

06/25/2021

Document Number:

688800024

FIELD INSPECTION FORM

 Loc ID 313561 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10506
 Name of Operator: SEELEY OIL COMPANY LLC
 Address: PO BOX 1058
 City: CORTEZ State: CO Zip: 81321
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224477	WELL	PR	03/01/2020	OW	083-06542	ISLAND BUTTE II UNIT 7-AH	EI

General Comment:

On June 17, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Seeley Oil Co. LLC Island Butte 2 #7-AH. For the most recent field inspection report of this facility, please refer to document #693903330. This site visit was in response to Complaint #200449437.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical injection system labeled paraffin inhibitor.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	AST labeled fresh water. Capacity is illegible.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Paraffin inhibitor chemical injection system.		
Corrective Action:			Date:

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER			37.543199,-108.962422
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	non-potable water	
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment berm. Tank is labeled fresh water.			
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 224477 Type: WELL API Number: 083-06542 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: Other Comment: _____

Sample Sample Type: VEGETATION
 Time: 06/17/21 (MM/dd/yyyy hh:mm) GPS: Lat _____ Long _____
 BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____
 Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____
 8270: _____ RCRA Metals: _____ 910-Metals: _____ PAH: _____
 Other: Herbicides
 Comment: 2 vegetation samples collected for analysis of herbicides.

Sample Sample Type: SOIL GRAB
 Time: 06/17/2021 11:30 (MM/dd/yyyy hh:mm) GPS: Lat 37.543074 Long -108.962646
 BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____
 Dissolved Methane: _____ Composition: YES Stable Isotopes: _____ 8260: _____
 8270: _____ RCRA Metals: _____ 910-Metals: YES PAH: _____
 Other: _____
 Comment: Sample ID #0617211130. Background sample collected from a depth of 0-3" to be analyzed for metals and inorganics.

Sample Sample Type: SOIL GRAB
 Time: 06/17/2021 11:15 (MM/dd/yyyy hh:mm) GPS: Lat 37.543160 Long -108.962621
 BTEX: YES TPH: YES Anion: _____ Captions: _____ General Chemistry: _____
 Dissolved Methane: _____ Composition: YES Stable Isotopes: _____ 8260: YES
 8270: YES RCRA Metals: _____ 910-Metals: YES PAH: YES
 Other: _____
 Comment: Sample ID #0617211115. Soil sample collected off location near dead vegetation at a depth of 0-8".

Sample Sample Type: SOIL GRAB
 Time: 06/17/2021 11:05 (MM/dd/yyyy hh:mm) GPS: Lat 37.543150 Long -108.962507
 BTEX: YES TPH: YES Anion: _____ Captions: _____ General Chemistry: _____
 Dissolved Methane: _____ Composition: YES Stable Isotopes: _____ 8260: YES
 8270: YES RCRA Metals: _____ 910-Metals: YES PAH: YES
 Other: _____
 Comment: Sample ID 0617211105. Soil sample collected off location near dead vegetation at a depth of 0-8".

Lab:

Lab Name

Pace Analytical

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical container.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 17, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Seeley Oil Co. LLC Island Butte 2 #7-AH. For the most recent field inspection report of this facility, please refer to document #693903330. This site visit was in response to Complaint #200449437.</p> <p>Two soil grab samples were collected to be analyzed for Table 915-1 constituents. One background soil sample was collected for metals and inorganics. Two vegetation samples were collected for analysis of herbicides.</p>	hughesjo	06/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800026	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464903