

Inspection Photos

Spill #480059

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #1 overview of spill area. The spill was reported as subsurface and occurred when an excavation clipped a line containing produced water and oil, the spill was reported as contained in the excavation. The area of impact is the disturbed soil near the tree shadow toward the back of photo.



Inspection Photos
Spill #480059
Inspection Date: 5/25/2021
All Photos taken by Kris Neidel



Photo #2 area of disturbed soil, it was not obvious where the failed flowline was

Inspection Photos
Spill #480059
Inspection Date: 5/25/2021
All Photos taken by Kris Neidel



Photo #3 Area of disturbed soil, it was not obvious where the failed flowline was

Inspection Photos

Spill #480059

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #4 It was reported that when the spill occurred, City of Rangely crews were attempting to access a valve on a water line. The blue PVC pipe contained a valve.

Inspection Photos
Spill #480059
Inspection Date: 5/25/2021
All Photos taken by Kris Neidel



Photo #5 closed valve, assumed to be a water line.