

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #1 Trackhoe parked at spill 479949 spill point

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #2 area at spill point had exposed flowlines and tees. Some salt staining was observed in excavation.



Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #3 photos of spill point, had exposed flowlines and tees. Some salt staining was observed in excavation.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**

**Spill #479949**

**Inspection Date: 5/25/2021**

**All Photos taken by Kris Neidel**



Photo #4 near spill point, looking north. Note PVC pipe in ground marking pothole.



**Inspection Photos**

**Spill #479949**

**Inspection Date: 5/25/2021**

**All Photos taken by Kris Neidel**



Photo #5 pot holes were observed, exposing flowline below. These potholes run from the spill point to the north.

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #6 close up of the nearest pothole from Photo #5. A flowline was observable, not obvious in photo #5.





Inspection Photos  
Spill #479949  
Inspection Date: 5/25/2021  
All Photos taken by Kris Neidel

Photo #7 close up of the pothole seen in the background of Photo #4

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #8 close-up of Photo #7, note flowline in pothole and salt staining.



Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #9, pothole marker seen in Photo #7 and Photo #8 looking north at flowline right-of-way marker.

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #10, spill point is to the left of photo in orange fenced area. The area where the spill daylighted (second time) is observable to the right of photo below trackhoe. This was the main spill path.



Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #11 spill path observed downstream of spill point, note: salt staining. The spill path was documented by Chevron in spill documents and COGCC in inspection doc #694500337.

Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #12 spill path observed downstream of spill point, note: salt staining. The spill path was documented by Chevron in spill documents and COGCC in inspection doc #694500337.



Inspection Photos

Spill #479949

Inspection Date: 5/25/2021

All Photos taken by Kris Neidel



Photo #13 spill path observed downstream of spill point, note: salt staining. The spill path was documented by Chevron in spill documents and COGCC in inspection doc #694500337.