

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2021

Submitted Date:

06/28/2021

Document Number:

701101635**FIELD INSPECTION FORM**Loc ID 417353 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments12 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Johnston, Tyson		Tyson.Johnston@oxbow.com	
		geops@oxbow.com	Inspection mail box
Donahue, Jessica	(303) 888-4862	jessica.donahue@oxbow.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Lang, Heather		Heather.Lang@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417354	WELL	TA	12/12/2013	OW	029-06109	SPU COCKROFT 1294 23-41D-H	TA
430938	WELL	SI	10/15/2012	GW	029-06112	SPU COCKROFT 1294 23-41D H1R	TA

General Comment:

COGCC Follow Up Inspection Report Summary
Follow up to 07/22/2020 inspection # 699801488
Uncorrected action item(s)

- No current form 4 requesting temporarily abandoned status.

Refer to warning letter #402070104 issued on 6/11/19.

- Unused equipment on location 3 tanks in tank battery out of service, unused compress gas vessel, pump jack, separators, disassembled equipment, etc..

During this inspection the following compliance issues were observed:

- Fallen tree across access road.
- Operator name and number not on tanks.
- No battery sign at tank battery.
- No legal description on well signs.
- Stained ground at tank battery and pump jack.
- Fence from gate to location and fence behind tank battery is damaged and knocked down.
- Heat elements out of tanks and tanks are open access of birds and wild life.
- SPU COCKROFT 1294 #23-41D H1R cellar full of fluid. Storm water in SPU COCKROFT 1294 23-41D-H rat hole. Containers not properly stored.
- Bradenhead inaccessible or not visible
- Unmarked deadmen.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Fallen tree across access road.		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	07/27/2021
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Operator name and number not on tanks.		
Corrective Action:	Comply with Rule 605.h.	Date:	09/30/2021
Type	BATTERY		
Comment:	No battery sign at tank battery		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	09/30/2021
Type	WELLHEAD		
Comment:	No legal description on well signs.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location 3 tanks in tank battery out of service, unused compress gas vessel, pump jack, separators, disassembled equipment, etc..		
Corrective Action:	Comply with Rule 606	Date:	10/22/2020
Type	OTHER		
Comment:	Stained ground at tank battery and pump jack.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	07/27/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Fence from gate to location and fence behind tank battery is damaged and knocked down.		
Corrective Action:	Repair fencing.	Date:	07/27/2021
Equipment:			
Type: Deadman # & Marked	# 1	corrective date	
Comment:	Unmarked deadmen		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	07/14/2021
Type: Pump Jack	# 1			
Comment:	Not in working condition.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	Bradenhead inaccessible or not visible			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date:	07/14/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:	Heat elements out of tanks and tanks are open access of birds and wild life.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		,
Comment:	Heat elements out of tanks and tanks are open access of birds and wild life.				
Corrective Action:	Cover opening to prevent entry of birds and other wild life.				Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 417354 Type: WELL API Number: 029-06109 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Mechanical Integrity Test Date: on 9/18/2019 Form 21 DocNum: 402187791
No current form 4 requesting temporarily abandoned status.
Refer to warning letter #402070104 issued on 6/11/19.

Corrective Action: A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. submit form 4.

Date: 09/30/2019Facility ID: 430938 Type: WELL API Number: 029-06112 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Mechanical Integrity Test Date: 5/18/2018 Form 21 DocNum: 401672731
No current form 4 requesting temporarily abandoned status.
Refer to warning letter #402070104 issued on 6/11/19.

Corrective Action: A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. submit form 4.

Date: 09/30/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Check Dams						
				Material Handling And Spill Prevention	Fail	5 gallon bucket of motor oil, gas can, other such
Compaction						
		Gravel				
		Compaction				
Gravel						
Seeding						
Ditches						

Comment: SPU COCKROFT 1294 #23-41D H1R cellar full of fluid. Storm water in SPU COCKROFT 1294 23-41D-H rat hole. Containers not properly stored.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101660	Inspection 701101635 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465308