

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW**

**Location ID: 335780**



**Photo #4160 from entrance to location.**



**Photo #4161 Location lacks stabilization**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



**Photo #4162 Location lacks stabilization**



**Photo #4163 Location lacks stabilization.**


## Inspection Photos

Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW

Location ID: 335780



**Photo #4165 No form of tracking BMP located at the entrance to location.**



**Location is approximately 460 feet from North Parachute creek.**

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC CHEVRON-66S96W /17SESW**

**Location ID: 335780**



**Photo #4166 Culvert and drainage that contributes to North Parachute Creek to the East of location and access road.**