

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2021

Submitted Date:

06/22/2021

Document Number:

696303376

**FIELD INSPECTION FORM**

Loc ID 318940 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 49407  
Name of Operator: KUGLER\* DEAN & JOE DBA D-J OIL COMPANY  
Address: P O BOX 72  
City: NEW RAYMER State: CO Zip: 80742

**Findings:**

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	
,		dakugler@yahoo.com	
Kugler, Dean		dlkug@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242543	WELL	SI	12/01/2015	OW	123-10334	MYERS F-1	SI

**General Comment:**

[This is a Follow-Up Inspection to FIR 696302630 dated 11.05.2020](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil at Tank Loadline. See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."		Date: <u>07/07/2021</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused Production Equipment STILL remains; Same Corrective Action Date is still active - Unused Heater Treater, 4 Deadman Anchors, Pumping Unit, Engine, Produced Water and Crude Oil Tanks.		
Corrective Action:	Comply with Rule 606		Date: <u>11/25/2019</u>
Type	WEEDS		
Comment:	Weeds are actively growing on the entire location, see photos		
Corrective Action:	Comply with Rule 606		Date: <u>11/20/2020</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead - Ready to Cut and Cap at surface		
Corrective Action:			Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.638020,-103.855310
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 242543 Type: WELL API Number: 123-10334 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well appears to have been Plugged and Abandoned around 07.08.2019. Well Bore at surface, now has a Metal Cap.  
Not yet Cut and Capped.  
Approved Form 6 2304070 dated 04.15.2019  
No Form 6 Subsequential has been submitted to date.

Corrective Action: Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. Per Rule 311.b. (1) Date: 12/04/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b></p> <p>On Tuesday 06/15/2020 at approximately 14:34, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Myers F-1 at Location #318940 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>The Well Bore is still at Surface, not yet Cut and Capped. Has been covered is a Metalplate.</p> <p>Stained Soil at Tank Loadline. See photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Corrective Action Date 07.07.2021</p> <p>Weeds are actively growing on the entire location, see photos. Comply with Rule 606. Corrective Action Date 11/20/2020.</p> <p>Multiple Unused Equipment: Separator, Pumping Unit, Horse??s Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tanks (2), Produced Water Tanks. Comply with Rule 606. Corrective Action Date 11/25/2019. Final Reclamation to begin 90 days after Plug and Abandonment.</p> <p>Well appears to have been Plugged and Abandoned around 07.08.2019, no Form 42 Notice of Plugging Operations was Submitted. Approved Form 6 #2304070 dated 04.15.2019. No Form 6 Subsequential has been Submitted to date. Wellbore is covered with Metal Plate at Surface, not yet Cut and Capped. Submit Subsequent Report of Abandonment, Form, 6. Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, shall be filed with the Director. Per Rule 311.b.(1). Corrective Action Date 12.04.2020 or to be determined by COGCC Engineering Staff.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection report.</p>	petrie	06/22/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402726279	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461234</a>
696303377	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461232">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461232</a>