

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2021

Submitted Date:

06/22/2021

Document Number:

699803265

FIELD INSPECTION FORM

Loc ID 334965 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 20 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275333	WELL	PR	07/31/2005	GW	045-13524	PA 22-6	PR
275334	WELL	PR	06/03/2005	GW	045-13523	PA 322-6	PR
275335	WELL	PR	07/06/2005	GW	045-13522	PA 422-6	PR
275336	WELL	PR	07/06/2005	GW	045-13521	PA 522-6	PR

General Comment:

COGCC Inspection Report Summary
On Tuesday 6/22/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PA-67S95W /6SENW, Location #334965 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

- 1) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 7/7/21.
- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 4		corrective date
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		

Comment:	All meter runs have been calibrated in the last year.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Separate from separators		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 4			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>275333</u>	Type:	<u>WELL</u>	API Number:	<u>045-13524</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275334</u>	Type:	<u>WELL</u>	API Number:	<u>045-13523</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275335</u>	Type:	<u>WELL</u>	API Number:	<u>045-13522</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275336</u>	Type:	<u>WELL</u>	API Number:	<u>045-13521</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction	Fail					Location lacks stabilization
Gravel	Fail					Gravel insufficient
		Gravel				
		Culverts				
Sediment Traps						
		Compaction				
Berms						
		Berms				
		Ditches				
Other	Fail					No form of tracking BMP at entrance to location

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 07/07/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	06/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402727314	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462123
699803266	Photos for Insp. #699803265	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462113