

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2021

Submitted Date:

06/24/2021

Document Number:

697601384**FIELD INSPECTION FORM**Loc ID 332971 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	
Gomez, Jason		jason.gomez@state.co.us	
Knop, Max	303-825-4822	MKnop@kpk.com	
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**General Comment:**

well only inspected in this report  
 Leak of combustible gas coming from welhead along rod.  
 portable 4 gas meter with PID indicates  
 >5% combustible gases (as methane)  
 <10% O2  
 H2S 25ppm  
 CO 5 ppm  
 PID reading of 2050 ppm (as isobutylene)  
 pressure of gas in wellhead not controlled by grease applied to rod

Leak was observed in previous inspection using FLIR camera on 5/21/2021  
 called 303-825-4822 at 1059am and instructed to call field office  
 called 303-833-5670 at 1101 am and Stephanie took message and relayed that she would let pumper know to go to well

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	see photo		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	present		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue, gas leak at rod coming out of wellhead, Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.		
Corrective Action:	per rule 608.e with leak found the operator has 24 hours to repair and stop leak Leak was present in previous inspection with no documentation provided to COGCC that leak was successfully repaired following that inspection.	Date:	06/25/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402728887	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463480">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463480</a>
697601385	well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463478">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463478</a>
697601386	rod with surplus of grease applied	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463479</a>