

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2021

Submitted Date:

06/24/2021

Document Number:

699304056

FIELD INSPECTION FORM

Loc ID 321465 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------------------|---------------------------------|
| , | | Cogcc.inspections@crestone pr.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 280436 | WELL | PR | 01/01/2021 | GW | 013-06520 | CLAY 13-26 | PR |

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Ag panel | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|--|-------|-----------------|
| Type: Bird Protectors | # 3 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # | | |
| Comment: | Card indicates that calibration is overdue, Provide calibration records or calibrate meter. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR). | | |
| Corrective Action: | Comply with Rule 430 | Date: | 07/24/2021 |
| Type: Bradenhead | # 1 | | |
| Comment: | appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|-----|--|-------|
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 4 | | |
| Comment: automation | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 150 bbl | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: shares containment with condensate tank | | | | |
| Corrective Action: | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 013-06520 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 280436 Type: WELL API Number: 013-06520 Status: PR Insp. Status: PR

Producing Well

| | |
|--------------------|-------|
| Comment: <u>PR</u> | |
| Corrective Action: | Date: |

BradenHead

Date of Last Brhd Test: 02/10/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Thursday 6/24/2021 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Clay 13-26 at API #05-013-06520 in Boulder County Colorado.</p> <p>While there, I observed a wellsite and tank battery, PR at the time of inspection. During this inspection the following possible compliance issues were observed: 430 Measurement of Gas: Card in meter box indicates that calibration is not current, CA date 7-24-2021. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report</p> | revasr | 06/24/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402729857 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464232 |
| 699304057 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464228 |