

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2021

Submitted Date:

06/24/2021

Document Number:

700702903**FIELD INSPECTION FORM**
 Loc ID 334837 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211366	WELL	PR	03/17/1999	GW	045-07126	SHIDELER 32-11	PR
269307	WELL	PR	02/06/2004	GW	045-09349	SHIDELER 32-6C (K32)	PR
269419	WELL	PR	02/05/2004	GW	045-09366	COUEY 32-5A1 (K32)	PR
269420	WELL	PR	02/27/2004	GW	045-09365	GRAHAM 32-12A (K32)	PR
269421	WELL	PR	02/24/2004	GW	045-09367	COUEY 32-5 (K32)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 6/23/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus K32, at Location # 334837 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

Some of the C/A's from previous inspection document # 700702480 have been completed.

During this inspection the following possible compliance issues were observed:

1. No tank battery signage from previous inspection has not been completed (C/A date remains the same 5/25/2021)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery signage from previous inspection has not been completed (C/A date remains the same 5/25/2021)		
Corrective Action:	Comply with rule 605.e	Date:	05/25/2021

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused chemical tank has been removed from previous inspection		
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	211366	Type:	WELL	API Number: 045-07126 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	269307	Type:	WELL	API Number: 045-09349 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	269419	Type:	WELL	API Number: 045-09366 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	269420	Type:	WELL	API Number: 045-09365 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	269421	Type:	WELL	API Number: 045-09367 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Berms						
Ditches						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. Location appears to be stabilized since last inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402729794	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464156
700702909	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464150