

Inspection Photos
Operator: Maralex Resources
API: 007-06208
Date: 6/29/2021



Photo 1. View the southwestern project area from the southwestern corner facing northward.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Several pipes, and farm implements are stored within the project area. Several pieces of scattered trash and debris observed around the well pad.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of pipes stores in the northeastern project area.



Photo 5. View of dense kochia growing in and around equipment areas.



Photo 6. View of reference area comprised of irrigated field, in a grazed vegetative condition.