

Inspection Photos

Operator: Maralex Resources
API: 007-06246
Date: 6/29/2021



Photo 1. View the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Vegetation here is largely comprised of weeds such as Russian knapweed, cheatgrass, and bindweed.



Photo 3. View of debris pile within the northeastern project area.



Photo 4. View of tubing, tires, and metal debris stored within the western project area.



Photo 5. View of culvert debris and Russian knapweeds within the southern project area.



Photo 6. View of dense Russian knapweeds and debris within the southern project area. Approximately 5000 individuals observed.




Photo 7. View of dense kochia growing in and around equipment areas.



Photo 8. View of reference area comprised of open field, with grasses such as crested wheatgrass.