

Inspection Photos

Operator: Morningstar Res.
API: 007-06202
Date: 6/29/2021



Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of saltcedar trees within the southern project area, need to be treated and removed.



Photo 5. View of perennial pepperweeds (approximately 100) within the southern project area. Need to be treated and controlled.



Photo 6. View of reference area comprised of open field, with grasses such as western wheatgrass, and foxtail barley, forbs such as wormwood, sedges, and cattails.