

Inspection Photos

6/30/2021

Operator: CHEVRON USA INC - 16700

Location ID: 398839

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 1: Photo taken from the south end of the Location, facing east. Photo shows example of areas where undesirable plant and noxious weed establishment was observed.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 2: Continued from photo 1. Photo shows example of undesirable plant and noxious weed establishment was observed on Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 3: Photo shows marker for the anchor on the northeast end of the Location is in disrepair.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 4: Photo shows germination transect #1 on the western interim areas of the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 5: Photo shows soil surface for the 50th point of the 1st germination transect; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 8 quadrats.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 6: Photo shows germination transect #2 on the northern interim areas of the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 7: Photo shows soil surface for the 50th point of the 2nd germination transect; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 8 quadrats.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 8: Photo shows soil surface for the 50th point of the 3rd germination transect on the northeast end of the Location; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 8 quadrats.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 10: Photo shows germination transect #2 on the northern interim areas of the Location.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 11: Photo shows soil surface for the 50th point of the 4th germination transect on the southeast end of the Location; desirable vegetative germination/establishment not observed, or negligible; approximately 1 seedling was observed for every 8 quadrats

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398839



Photo 12: Photo taken from the eastern interim areas of the Location, facing south. Photo shows example of areas where undesirable plant and noxious weed establishment was observed.