

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2021

Submitted Date:

07/01/2021

Document Number:

696202878

FIELD INSPECTION FORMLoc ID 397191 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Chris		spwu@chevron.com	All Inspections per Olson
Olson, Andrew		andrewolson@chevron.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229146	WELL	PA	02/25/1987	ERIW	103-06230	UNION PACIFIC 52-29	RI
397191	LOCATION	AC	04/14/2009		-	UNION PACIFIC-62N102W 29SEW	RI

General Comment:

On 6/30/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Chevron USA Inc's UNION PACIFIC #52-29 location in Rio Blanco County, Colorado.

This inspection is a follow up to #680101530 dated 02/15/2017, #692401238 dated 7/31/2019, and #696202230 dated 1/19/2021 to document compliance for the following corrective actions:

-Comply with 1004 Rules

This inspection is also a followup to resolution #402593688 stating CA has been completed.

It was observed that additional reclamation has been performed.

The following compliance issues were observed during this inspection:
1004.e: Noxious weeds

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	229146	Type:	WELL	API Number:	103-06230	Status:	PA	Insp. Status:	RI
Facility ID:	397191	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present Fail Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Previous inspection observed concrete pad/debris remaining on the Location. Inspections required Operator to comply with 1004 Rules by 11/1/2019.

It was observed in this inspection that additional reclamation has been performed. Reclamation Specialist conducted a germination transect and observed that desirable plant germination was not occurring over the reclamation area (~0.05 seedlings per 1/2 sq. meter); additional seeding likely required; a followup inspection will be conducted in a future growing season to determine compliance with 1004 rules. This corrective action has been addressed.

Noxious weeds (Halogeton) observed establishing on the reclamation area.

Corrective Action: **Comply with Rule 1004.e**

Date **07/15/2021**

Overall Final Reclamation

In Process

Well Release on Active Location ☐

Multi-Well Location ☐

COGCC Comments

Comment	User	Date
Additional reclamation performed tied to interim reclamation for the Union Pacific 52A-29 Location. See FIR 696202875 for additional information.	trujilloam	07/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202879	Data Sheet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5469718
696202880	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5469719