

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4' barb wire / fabricated fencing around wellhead

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: automation

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|----------|---------|----------------------------|
| PRODUCED WATER | 1 | 100 BBLS | Open Top | | , |
| Comment: adequate netting at time of inspection | | | | | |
| Corrective Action: <input type="text"/> | | | | | Date: <input type="text"/> |

| | |
|------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| | | | | |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | shares containment with oil tank | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | |
|------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | |
|--------------------|-------|
| Venting: | |
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

| | |
|--------------------|-------|
| Flaring: | |
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 202713 Type: WELL API Number: 001-08118 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/22/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|----------------|-------------------|
| <u>At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast, warm.</u> | <u>medinaj</u> | <u>07/01/2021</u> |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|------------------|-------------|---|
| <u>699502953</u> | <u>pics</u> | <u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5469920</u> |