

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2021

Submitted Date:

06/28/2021

Document Number:

697601396**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479834	SPILL OR RELEASE	AC	04/28/2021		-	Suckla Farms E #2 Flowline	EI

**General Comment:**

[steel panel fencing around spill area still in place as shown in attached photo.](#)

[Sorbent booms observed in main excavation in effort to minimize horizontal transport of crude oil in precipitation event.](#)

[No barrier to prevent infiltration of crude oil and associated impacts to deeper soils and to shallow groundwater at site as likely happened in recent precipitation event.](#)



**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 50

Comment: observations to date at site indicate that operator is not in compliance with Rule 912.a(2).

Corrective Action:

Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Provide timetable of actions to be taken to comply with Rule 912.a(2) by means of supplemental form 19 or by initiating a site investigation and remediation plan form 27 initial.

Date: 07/06/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402731403	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465562</a>
697601397	fenced excavation, visible and olfactory soil impacts noted	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465560</a>
697601398	visible impacts to soils in sidewall of open excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465561">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465561</a>