

Inspection Photos
Operator: Hilcorp
API: 067-07674
Date: 7/2/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View the southern project area from the southwestern corner facing eastward. Little desirable vegetation here. Vegetation is largely field bindweed. Germination not observed.



Photo 3. View of wattles and erosional channeling in the southern project area. Wattles are not an adequate BMP for this area. Little desirable vegetation present.



Photo 4. View of cobble BMPs along the access road, full of sediment and not functioning. These BMPs are not adequate and need to be installed using good engineering practices.



Photo 5. View of the northern project area facing eastward. Revegetation is progressing in this portion with western wheatgrass and smooth brome.



Photo 6. View the reference area comprised of Gambel oak and mountain mahogany shrubland with sagebrush, western wheatgrass, and smooth brome in the understory.