

Inspection Photos
Operator: Holcomb
API: 067-06545
Date: 7/2/2021



Photo 1. View the project area from the southern corner facing center.



Photo 2. View the western project area from the southern corner facing northwestward. Little desirable vegetation here. Vegetation is largely field bindweed.



Photo 3. View of erosional channeling within the northeastern project area. Wattles are full of sediment and degrading. Green plastic debris present. These BMPs are not adequate and need to be installed using good engineering practices.



Photo 4. View of example of green plastic netting within the eastern project area, several pieces observed across northeastern and eastern project area.



Photo 5. View of erosional rilling within the northwestern project area. Sediment piles observable.



Photo 6. View the reference area comprised of Gambel oak and mountain mahogany shrubland with sagebrush, western wheatgrass, and smooth brome in the understory.