

Inspection Photos

API: 055-06278

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos



Photo 1. Facing southwest along the former access road. The road was not recontoured and reclaimed. There is erosion occurring along the road and the rock check dams are displaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos



Photo 2. Facing southwest along the former access road which was not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos



Photo 3. Facing southwest toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos



Photo 4. Facing northeast toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos




Photo 5. South side of the location facing southwest. The area under red line consists of weeds and arrow points to Scotch thistle noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021

Inspection Photos



Photo 6. Facing southeast at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Blue fringed sage, among other native species as well as weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 7/2/2021