

Inspection Photos  
Operator: Simcoe  
API: 067-08664  
Date: 7/2/2021



Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with smooth brome.



Photo 3. View of erosional channel forming (approximately 6 inches deep and 1.5 feet wide) and sediment deposition within the southwestern project area (facing upslope). Inset shows channel flowing off of the project area and downcutting.



Photo 4. View of erosional channel forming and sediment deposition within the southern project area (facing downslope).



Photo 5. View the reference area comprised of black sagebrush shrubland with gambel oak, western wheatgrass, and squirreltail.