

# Inspection Photos

API: 071-06347

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** The road was regraded and gravel was applied to areas of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021

## Inspection Photos



**Photo 2.** It appears recent rain events have deposited sediment into the culverts. Ongoing maintenance needs to be performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021

## Inspection Photos



**Photo 3.** Additional grading will be needed to drain stormwater toward the culvert in this area. Stormwater is already accumulating on the road shown at red arrow.  
Lat/Long:37.06585,-104.93198.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021

## Inspection Photos



**Photo 4.** Facing southeast toward the access road. Stormwater is directed toward the culvert shown at red arrow. Sediment is already filling into this area which will require ongoing maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021

## Inspection Photos



**Photo 5.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 7/7/2021