

Inspection Photos

API: 071-08927

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021

Inspection Photos



Photo 1. Facing southeast along the access road. The road is not stabilized and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021

Inspection Photos



Photo 2. Facing southeast further along the access road. The road is not stabilized and there are signs of erosion and vehicle rutting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021

Inspection Photos



Photo 3. Facing southwest at the location. Erosion of the cut slope is directing sediment down towards the road. This area needs to be stabilized erosion controls are needed (e.g. sediment trap)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021

Inspection Photos



Photo 4. Facing toward the equipment. A panel is laying on the ground and needs to be re-installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021

Inspection Photos



Photo 5. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 7/7/2021