

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2021

Submitted Date:

07/09/2021

Document Number:

696104690

**FIELD INSPECTION FORM**

Loc ID 310892 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297567	WELL	SI	09/01/2017	OW	123-27193	KEHN USX AA 01-06	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Shut-In | SI.  
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs  
(310894, 310892).  
(Well(s): 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894  
for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:					Date:	
<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.519004,-104.390068	
Comment:		Centralized Battery serves 2 Location IDs (310894, 310892). Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894 for Battery / Facility, Equipment info.				
Corrective Action:					Date:	
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 297567 Type: WELL API Number: 123-27193 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.  
COGCC records indicate last production: 07/2016.  
SI/TA well per variance doc. #401474555. (NOBLE).  
Yellow LTSI tag for SI/TA status present at wellsite.  
Locked-Out, Tagged-Out | LOTO.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 05/01/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On THU 07/08/2021 at approximately 15:57 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: KEHN USX AA-66N63W /1SENW                      Location ID: 310892                      Well Name(s): Kehn USX AA 01-06.                      API: 05-123-27193.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Shut-In   SI.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310894, 310892).                      (Well(s): 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696104688 and/or Location ID #310894 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/09/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696104691	Site photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475905">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475905</a>