

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 272452 Type: WELL API Number: 071-08076 Status: SI Insp. Status: PR

Producing Well

Comment: PR Flow line vavles appear to be open.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Submit reports.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>This is a follow up inspection per doc#695103944. At time of inspection it appeared operator has addressed the issue in the previous inspection but this appears to be an on going issue due to the weather conditions. At the time of this inspection it was raining and fluid in compressor skid was about to run over on to ground. Need to address as soon as possible.</u>	silverr	07/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505314	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5476660