

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2021

Submitted Date:

07/12/2021

Document Number:

699304088**FIELD INSPECTION FORM**Loc ID 318388 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241204	WELL	PR	08/01/2019	OW	123-08992	CARL R. DEEPE C 2	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	all weeds growing along access road			
Corrective Action	Comply with Rule 606			Date: 06/24/2021
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	tall weeds growing around location ROW			
Corrective Action:	Comply with Rule 606			Date: 06/24/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	hog fence			
Corrective Action:				Date:
Type	OTHER			
Comment:	ancillary equipment has fabricated steel pipe			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	electric motor			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box and transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241204 Type: WELL API Number: 123-08992 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/28/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 25 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Monday 7/12/2021 at approximately 1310 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up to inspection Doc # 699303978.

Carl R Deepe C 2 at Location#318388 in Weld County Colorado.

While there, I observed a wellsite, PR at the time of inspection.

During this inspection the following possible compliance issues were observed and are now delinquent:

606 Housekeeping: Weeds growing tall down access rd. and around location ROW, CA date

6-24-2021.

See attached photos.

Location: dry, Weather: clear.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

revasr

07/12/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304089	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5477027