

## Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NWSE

Location ID: 324311



Network time is not synchronize  
Local: Jul 12, 2021 at 12:17:48 PM MDT



Network: Jul 12, 2021 at 12:34:35 PM MDT  
Local: Jul 12, 2021 at 12:34:35 PM MDT

Photo #4382 from entrance to location.

Photo #4383 Flow line heating insulation open ended and not capped.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NWSE

Location ID: 324311



**Photo #4384 Flow line heating insulation open ended and not capped.**