

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P6-22-1 /**  
**Location ID: 324394**



**Photo #4390 from entrance to location.**

**Photo #4391 from entrance to location.**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P6-22-1 /**  
**Location ID: 324394**



**Photo #4392 Flow line heating insulation open ended and not capped.**



**Photo #4393 Location lacks stabilization.**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC P6-22-1 /**  
**Location ID: 324394**



**Photo #4394 Location lacks stabilization.**



**Photo #4395 No form of tracking BMP located at the entrance to location.**