

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NWN

Location ID: 324328



Photo #4398 from entrance to location.



Photo #4399 heating insulation open ended and not capped.

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NWNE

Location ID: 324328



Photo #4403 Trash on location.



Photo #4400 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1NWNE

Location ID: 324328



Photo #4401 Location lacks stabilization.



Photo #4402 No form of tracking BMP located at the entrance to location.