

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2021

Submitted Date:

07/07/2021

Document Number:

694500354**FIELD INSPECTION FORM**Loc ID 324631 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa	720-257-2302 303-244-8114	ABeard@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159760	SPILL OR RELEASE	CL	01/14/2015		-	SPILL/RELEASE POINT	EI
212201	WELL	SI	09/01/2020	OW	057-06094	TITANIUM 26-10-7HI & 2	EI
324631	LOCATION	AC			-	TITANIUM-67N81W 26NWSE	EI

General Comment:

On 6/17/21 COGCC staff, Kris Neidel inspected the Titanium well, pit 111692 is being closed as a part of REM project 15761 . Weather was 80 degrees and dry. No recent evidence of wildlife or livestock was present at the time of inspection. All production equipment has been removed from location. Material from pit has been stockpiled on pad surface. No obvious hydrocarbon staining was detectable in pit (smell or staining). COGCC has been told that the pit has been sampled. On the next quarterly report these results should be provided via Form 27. This remediation project should be completed no later than this fall. Stockpiled soil shall be removed immediately. See attached photos.

Inspected Facilities

Facility ID:	<u>159760</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-----------------	-------------	----------	---------	-----------	---------------	-----------

Facility ID:	<u>212201</u>	Type:	<u>WELL</u>	API Number:	<u>057-06094</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

Facility ID:	<u>324631</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-----------------	-------------	----------	---------	-----------	---------------	-----------

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Inadequate	40.547198	-106.449302
Comment	Material from pit has been stockpiled on pad surface.			
Corrective Action	Stockpiled soil shall be removed immediately.			Date: 07/14/2021

Spill/Remediation:

Comment:				
Corrective Action:				Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402740545	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472889
694500355	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472888