

**Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)**



Photo 1 – Spill area 7/9. Excavation is open and surface soils surrounding excavation have been scraped.



Photo 2 – Spill excavation 7/9. Impacts remain visible in-situ and free product is visible in excavation.

Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)



Photo 3 – Spill excavation 7/9; free product is visible in excavation.



Photo 4 – Soil staining on surface in scraped area.

**Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)**



Photo 5 - Spill area 7/12.



Photo 6 – Spill excavation 7/12; free product is visible in excavation and soil impacts remain in-situ.

**Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)**



Photo 7 - Spill excavation 7/12; soil impacts remain in-situ.



Photo 8 – Impacted soil being placed on plastic liner then transported off-site.