

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2021

Submitted Date:

07/14/2021

Document Number:

696303420

FIELD INSPECTION FORMLoc ID 317497 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 42950

Name of Operator: INDUSTRIAL GAS SERVICES INC

Address: 4891 INDEPENDENCE ST STE 200

City: WHEATRIDGE State: CO Zip: 80033

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	
,		igsinc@att.net	All Inspections
Burn, Diana		diana.burn@state.co.us	
Wolfe, Stephen		stephen.wolfe@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238366	WELL	SI	03/01/2016	GW	123-05210	HENDERSHOT 1	SI

General Comment:

This is a Follow-UP WELL & BATTERY Inspection to FIR 696301780 dated 05.04.2020 and FIR 696302590 dated 10.26.2020
Follow-Up to NOAV 402668910 dated 04.23.2021
Well: SI
Entire Battery & Equipment is Shut-Down.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Drum at Wellsite has been removed from Location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds have now started Re-growth. See photos. Please keep regular maintenance going to keep Weed vegetation from growing.		
Corrective Action:	Comply with Rule 606	Date:	07/30/2021
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Wellhead. See photos		
Corrective Action:	Comply with Rule 606	Date:	07/16/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment has been removed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained Soil at Heater Treater and Gas Engine Site have been removed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead has NOW been plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	TA Wellhead		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	Wildlife Screen has been installed on Heater Treater Stack		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	500 BBLS	STEEL AST		40.459683,-104.158554
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms have been repaired			
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 238366 Type: WELL API Number: 123-05210 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Operator completed MIT on 06.23.2021. Held pressure at 353# for 15 mins.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: _____

Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____

Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Bradenhead has been plumbed to surface. Test Completed on 06.23.2021 and Form 17 Submitted around 07.12.2021

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID:

Lat: 40.459900Long: -104.159000Reference Point: SE

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:Netting Type: Mesh

Netting Condition:

Comment:

Hard to observe Pit Netting Repairs due to Weed Growth.
 Remove Weeds and Manage future grow. See photos
 From prior FIR:
 Gaps around edges of pit netting. Maintain netting.
 Net or fence pit to prevent access per rule 909.f.
 Corrective Action date: 05/07/2018.

Corrective Action

Net or fence pit to prevent access per rule 909.f.
 Remove and maintain Weed Growth per Rule 606

Date: 05/07/2018

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On Wednesday 07/07/2021 at approximately 11:47. I, Field Inspector, Erica Petrie, conducted an on-site Follow-Up Inspection at: Operator Name: INDUSTRIAL GAS SERVICES INC. Location Name: HENDERSHOT #1 API: 05-123-05210 Location ID: 317497 Location County: Weld County, Colorado</p> <p>While there, I observed: Well - SI Entire Battery & Equipment is Shut-Down.</p> <p>Follow-UP WELL & BATTERY inspection to FIR 696301780 dated 05.04.2020 and FIR 696302590 dated 10.26.2020 Follow-Up to NOAV 402668910 dated 04.23.2021 Prior Corrective Action dates remain applicable. 2 of 9 - Corrective Actions NOT addressed. 1 New Corrective Action found.</p> <p>1.) Stained soil at Heater Treater has been removed.</p> <p>2.) Gas Engine and Housing have been removed. Stained soil has removed</p> <p>3.) Berm Integrity has been repaired</p> <p>4.) Unused Equipment (Pipe, Fittings, Trash) at Pumping Unit & Manifold area E. of Pit have been removed.</p> <p>5.) Well is Shut-In. MIT preformed on 06.23.2021. Held pressure at 353# for 15 minutes.</p> <p>6.) Unmarked container at Pumping Unit has been removed</p> <p>Bradenhead has NOW been Plumbed to surface. Bradenhead Test/Form 17 has been completed.</p> <p>Corrective Actions NOT Complete:</p> <p>1.) Weed encroachment at Pit Area, Wellsite & Tank Battery. Remove, manage, & control weeds around the wellsite. Comply with Rule 606. Corrective Action date: 07/30/2021. See photos.</p> <p>2.) Gaps around edges of pit netting. Hard to observe Pit Netting Repair due to Weed growth. Remove Weeds and Manage future grow per Rule 606. Maintain netting. Net or fence pit to prevent access per rule 909.f. See photos. Corrective Action date: 05/07/2018.</p> <p>** New Corrective Action - Unmarked Riser at Wellhead. Mark Riser per Rule 606. Comply with Rule 606. Corrective Action date: 07/16/2021. See photos</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	07/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303421	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5478773