

Inspection Photos
Operator: Simcoe
API: 067-07172
Date: 7/13/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing in portions with squirreltail and crested wheatgrass. Other portions remain sparse and weedy and need to be monitored.



Photo 3. View the southern project area from the southwestern corner facing eastward.



Photo 4. View the reference area comprised of sagebrush and greasewood shrubland with Indian ricegrass, squirreltail, prickly pear, fourwing saltbush, and purple threeawn.