

Inspection Photos  
Operator: Simcoe  
API: 067-05577  
Date: 7/13/2021



Photo 1. View the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing in portions with squirreltail, rubber rabbitbrush, and crested wheatgrass. Other portions remain sparse and weedy and need re-seeding




Photo 4. View of dense Russian thistle and debris within the western project area. Little desirable vegetation observed here. Weeds are obstructing desirable vegetation establishment.



Photo 5. View the reference area comprised of pinyon and juniper woodland with understory of prickly pear, squirreltail, sagebrush, and gambel oak.